

Anderson Home Inspection Service, LLC

18:20 June 08, 2018
License HI 267

Page 1 of 25
Sample Lintel 04-22-2018.alb6



#1

Date Slab 4.16.18	Insp. (Signature)	4/16/18 Date Elec Rough-In	Insp. (Signature)	4/12/18 Date Sewer	Insp. (Signature)	Date Solar Fi
Date Stem Wall	Insp. (Signature)	Date Other	Insp. 205 (Signature)	Date Water	Insp. (Signature)	Date Other
Date Beam/Lintel/Col	Insp.	Date Other	Insp. (Signature)	Date Tub Set	Insp.	D
Date Sheathing/Nail	Insp.	Date Other	Insp.	Date 2nd Rough-In	Insp.	

#2 2 dowels improperly placed. Missing footer dowels: at patio, left side near front, right side near center, left front of garage



#3 Missing total of 4 footer dowels



#4 Missing total of 4 footer dowels



#5 Missing total of 4 footer dowels



#6 Missing total of 4 footer dowels



#7 Missing total of 4 footer dowels



#8



#9 Black: dowels placed improperly. Red: missing footer dowels



#10



#11



#12



#13 Dowels placed improperly at slab pour at 2 places



#14 Dowels placed improperly at slab pour at 2 places



#15 Dowels placed improperly at slab pour at 2 places



#16 Dowels placed improperly at slab pour at 2 places



#17 Dowels placed improperly at slab pour at 2 places



#18 Dowels placed improperly at slab pour at 2 places



#19 Footer dowel missing. All dowels were present at footer inspection



#20 Missing total of 4 footer dowels



#21 Missing total of 4 footer dowels



#22 Missing total of 4 footer dowels



#23 Missing footer dowel at garage



#24



#25



#26



#27



#28



#29



#30



#31



#32



#33



#34



#35



#36



#37



#38



#39



#40



#41



#42



#43



#44



#45



#46



#47



#48



#49



#50